



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
DASARAHALLI		13		Mallasandra			
Street ID		Street Name		Significant Landmark			
W0271		Ambedkar Nagar Slum		St. Marys School			
Segment No.		Total Length (m)					
13/S-W0271/S020951		275.02					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	275.02	77.513721	13.050471	77.513200	13.048038	1st main road	SWD
Work Details							
History of Road / Lane / Circles							
Name of the Work		Sanctioned Estimated Amount (Rs.)			Sanctioned Year		
Improvements to drains & footpath 4th cross and adjoining roads of Kalyanaganga W/s in Ward No.13, in Shettyhalli Sub Division		1800000			2015		
Year	Type of Work		Other Work Type				
2014 - 2015	Drain Maintenance						
Tender	Work Details			Job No. / Work Code			
Tender				013-15-000015			
Work Order No.	Work Order Date		Period of Extension				
EE/DD/WO/298/14-15	16/03/2015						
Defect Liability Period From	Defect Liability Period To		Multiple road involved with the same Job No/ Work Code #				
			No				
Contractor Details							
Name of Contractor		Contractor Reg No (BBMP/PWD)			Expenditure Booked \ Released (Rs)		
N Shivananda					0.00		
Phone No.	E-Mail ID						
7795655296							

(Signature)

Zone: DASARAHALLI

Ward No: 13

Ward Name: Mallasandra

Street ID: W0271

Date: 05/11/2016

Time: 14:13:37

RH20161105141337

Page 1 of 2

Field Inspection Details

Number of Trees

0

Any Other Information

Name

Nagabhushan

Date of Inspection

05/11/2016

Remarks

Category

Image

Photo Remark

Drain Condition



This photo seems out of range.

Remarks

Designation

Approver Name

Date

Target Date

Remark

Zone: DASARAHALLI

Ward No: 13

Ward Name: Mallasandra

Street ID: W0271

Date: 05/11/2016

Time: 14:13:37

RH20161105141337

Page 2 of 2